COVERPLAST

VERNIS AUTONETTOYANT POUR HÉLICES ET TOUS MÉTAUX IMMERGÉS

FICHE TECHNIQUE

FR

CRYSTAL PROP ELLERS

DESCRIPTION :
- Traitement bi-composant à haute ténacité
- Finition transparente avec un aspect brillant.

PROPRIÉTÉS :
- S'applique sur toutes surfaces métalliques immergées
- Très résistant aux frottements
- Très bon rendement
- Parfaite résistance aux UV
- Très résistant aux agents chimiques

STOCKAGE :
A conserver à température ambiante dans un espace sec et frais

CONDITIONNEMENT :
- Kits de 100, 200, 500 ou 1000 ml
- Kit contient 2 flacons, composant A et B

COULEUR :
- Le produit est translucide

APPLICATION :

1. Préparation du support :
- Bien nettoyer et dégraisser le support
- Poncer pour une bonne accroche
- Crystal Prop, composant A + B: mélange de 1 : 1

2. Application
- 1 seule couche
- Pistolet à gravité avec buse de 1.2, pression HPS 4-5 bars, HVLP 2-3 bars
- Au pinceau

3. Temps d'évaporation :
- 60'- 90' min selon température extérieure

4. Séchage :
- Hors poussière : 4H à 20°
- Sec au touché : 3H à 20°
- Sec à manipulé : 12H à 20°
- Séchage complet : 48H à 20°

Un séchage à une température supérieure à 50° endommage le produit et ses qualités d'adhérence.

COVERPLAST

SELF-CLEANING VARNISH FOR PROPELLERS AND ALL IMMERSED METALS

DATA SHEET

EN

CRYSTAL PROPELLERS

DESCRIPTION :
- Two-component, high grip bonding
- Transparent finish with a glossy appearance

PROPERTIES :
- Can be applied to all immersed metal surfaces
- Very resistant to friction
- Very good performance
- Perfect UV resistance
- Very resistant to chemicals
- Flexible

STORAGE :
Store at room temperature in a cool, dry place

PACKAGING :
- 100, 200, 500 or 1000 ml bottles kit
- Kit contains 2 bottles, component A and B

COLOUR :
- The product is translucent

APPLICATION :

1. ***Surface Preparation*** :
   - Clean and degrease the surface thoroughly
   - Sand for a good adhesion
   - Crystal Prop, component A + B: 1:1 mixture

2. ***Application***
   - Single coat application
   - Gravity spray gun with 1.2 nozzle, pressure HPS 4-5 bars, HVLP 2-3 bars
   - Brush application

3. ***Evaporation Time*** :
   - 60'- 90' min depending on outside temperature

4. ***Drying*** :
   - Dust free: 4H at 20° C
   - Touch dry: 3H at 20° C
   - Dry to handle: 12H at 20° C
   - Fully dry: 48H at 20°.

Drying at temperatures above 50° will damage the product and its adhesion qualities.